



(B)

 सत्यमेव जयते	<b>GOVERNMENT OF INDIA</b> <b>CENTRAL PUBLIC WORKS DEPARTMENT</b> <b>Office of the Assistant Engineer,</b> <b>Kannur Central Sub Division-IV,</b> 2 <sup>nd</sup> Floor Bldg No. CB-40/1143, Abhilash Tourist Home Building Railway Station Road, Kannur,	 CPWD
---	--	---

No.23(141)/KaCSD IV/2020 / 73

Date: 14/01/2021

To

The Asst. Administrative Officer (Estate)  
CPCRI, Kasaragod


Sir,

Sub : Issue of Safety Certificate of Kendriya Vidyalaya No.1 at CPCRI Campus,  
Kasaragod reg.

Ref : Letter No.E.No.40(3)CPWD/2019-Estate dated 21.12.2019


Please find enclosed herewith the Safety Certificate of the above building for  
further necessary action.


Yours faithfully

  
Assistant Engineer  
Kannur Central SD-1V  
CPWD, Kannur.

Copy to:

1. The Executive Engineer-Kannur,CPWD, Kannur for information


  
Assistant Engineer IV



## SAFETY CERTIFICATE

The above building was inspected by me on 06/01/2021 and the overall safety for time being is safe for intended use. Apart from this view the following points are observed and recommended for further action from your end.

1. The Western block of the school building is a load bearing structure of approximately 35 years old which has completed the life expectancy as per CPWD Works Manual and needed to be replaced with New structure.
2. At the North end of the building, the laterite column and wall are having huge cracks because of the overload of the roof which was made by heavy 'I' sections and subsequent gradual settlement of the structure.
3. It was found that the 8 Nos trees are dangerous for the newly constructed Eastern block as the roots will damage the foundation as well as flooring. Constructing Boundary wall will not be sufficient as the trees are of big size. Hence it is recommended that the above trees may be cut from the site.



Assistant Engineer  
Kannur Central SD-1V  
CPWD, Kannur.

